

SPECIFICATIONS

Straight Moldboards

Power Reversible Models

PLOW MODEL	PLOW LENGTH	PLOW HEIGHT	TRIP SPRINGS	CUTTING SWATH @ 35°	MOLDBOARD OVERHANG	WEIGHT APPROX.
10SBPR2	10'	36"	3	8' - 2.25"	10"	1859#
11SBPR2	11'	36"	3	9' - 0"	10"	1943#
12SBPR2	12'	36"	4	9' - 9"	10"	2001#
10HSBPR2	10'	42"	4	8' - 2.25"	11"	1983#
11HSBPR2	11'	42"	4	9' - 0"	11"	2056#
12HSBPR2	12'	42"	5	9' - 9"	11"	2122#
10EHSBPR2	10'	48"	4	8' - 2.25"	12"	2092#
11EHSBPR2	11'	48"	5	9' - 0"	12"	2170#
12EHSBPR2	12'	48"	5	9' - 9"	12"	2269#

Power Circle Latch Models

PLOW MODEL	PLOW LENGTH	PLOW HEIGHT	TRIP SPRINGS	CUTTING SWATH @ 35°	MOLDBOARD OVERHANG	WEIGHT APPROX.
10SBPCL	10'	36"	3	8' - 2.25"	10"	1779#
11SBPCL	11'	36"	3	9' - 0"	10"	1863#
12SBPCL	12'	36"	4	9' - 9"	10"	1921#
10HSBPCL	10'	42"	4	8' - 2.25"	11"	1903#
11HSBPCL	11'	42"	4	9' - 0"	11"	1976#
12HSBPCL	12'	42"	5	9' - 9"	11"	2042#
10EHSBPCL	10'	48"	4	8' - 2.25"	12"	2012#
11EHSBPCL	11'	48"	5	9' - 0"	12"	2090#
12EHSBPCL	12'	48"	5	9' - 9"	12"	2189#

Power Reversible Tube Table Plows

PLOW MODEL	PLOW LENGTH	PLOW HEIGHT	TRIP SPRINGS	CUTTING SWATH @ 35°	MOLDBOARD OVERHANG	WEIGHT APPROX.
10SBPRT	10'	36"	3	8' - 2.25"	10"	1859#
11SBPRT	11'	36"	3	9' - 0"	10"	1943#
12SBPRT	12'	36"	4	9' - 9"	10"	2001#
10HSBPRT	10'	42"	4	8' - 2.25"	11"	1983#
11HSBPRT	11'	42"	4	9' - 0"	11"	2056#
12HSBPRT	12'	42"	5	9' - 9"	11"	2122#
10EHSBPRT	10'	48"	4	8' - 2.25"	12"	2092#
11EHSBPRT	11'	48"	5	9' - 0"	12"	2170#
12EHSBPRT	12'	48"	5	9' - 9"	12"	2269#

Manual Reversible Models

PLOW MODEL	PLOW LENGTH	PLOW HEIGHT	TRIP SPRINGS	CUTTING SWATH @ 35°	MOLDBOARD OVERHANG	WEIGHT APPROX.
10SBRH	10'	36"	3	8' - 2.25"	10"	1775#
11SBRH	11'	36"	3	9' - 0"	10"	1860#
10HSBRH	10'	42"	4	8' - 2.25"	11"	1900#
11HSBRH	11"	42"	4	9' - 0"	11"	1975#

The Gledhill Road Machinery Co.

www.gledhillonline.com • P.O. Box 567 • Galion, Ohio 44833 • phone: 419-468-4400 • fax: 419-468-6621